




RIVER MILE 10.9 REMOVAL ACTION WATER QUALITY MONITORING PROGRAM WEEKLY REPORT

Summary of water quality monitoring for the week ending September 8, 2013


Dredging operations, which began on August 3, 2013, are being continuously monitored to ensure that water quality is maintained at acceptable levels. To monitor water quality, a number of sampling locations have been established as shown on the map below.


Operations were conducted within acceptable water quality limits.



Water Quality Monitoring Data

Weekly Turbidity (NTU)		
	Average	Stan. Dev.
Buoy #1	13	7
Buoy #2	21	14
Buoy #3	11	8
Buoy #4	9	5





Water Quality Monitoring Locations